

Traffic Engineering Manual Revisions

Date	Chapter/Section	Page Number(s)
8/7/2009	18.3.2 #1 Speed Determination - Ball Bank Indicator changed from 16 to 12 degrees.	18.3(7) - 18.3(8)
8/7/2009	18.5.1.1 #12 No services - language change for the No services signs.	18.5(1) - 18.5(2)
8/7/2009	Figure 18.8H - Multiple Chevron Sign Barricade - dimensions changed in drawing	18.8(11) - 18.8(12)
8/7/2009	Figure 19.5C - School Crossings - included "sharks teeth" in drawing	19.5(5) - 19.5(6)
8/7/2009	Figure 19.5D - Typ. Pavement Markings at Highway/RR Grade Crossings - Note 1 changed to agree with MUTCD guidelines.	19.5(7) - 19.5(8)